

10/66/862 11-17-05

C-ofC.

Express Mail No. EV 533 716 021 US

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent:

Huy Nguyen et al.

Patent No.:

6,960,952 B2

Issued:

November 1, 2005

For:

Configuring and Selecting a

Attorney Docket No: 60809-0133-US

Duty Cycle for an Output

Driver

REQUEST FOR CERTIFICATE OF CORRECTION

Certificate
NOV 2 1 2005
Of Correction

Certificate of Corrections Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

Upon review of the subject patent, Patentee's attorney discovered five errors in the claims on the part of the Patent Office. Patentee's attorney requests correction of the issued patent, a Form PTO 1050 Certificate of Correction is enclosed in duplicate.

No fee is believed to be due with this paper; however, the Commissioner is authorized to charge any required fees or credit any overpayments to our Deposit Account No. 50-0310 (order no. 60809-0133-US). A copy of this sheet is enclosed.

Respectfully submitted,

Date:

November 15, 2005

UMA

31,066

(Reg. No.)

MORGAN, LEWIS & BOCKIUS LLP

2 Palo Alto Square

Gary S. Williams

3000 El Camino Real, Suite 700

Palo Alto, California 94306

(650) 843-4000

,NOV 2 2 2005

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,960,952 B2

DATED

November 1, 2005

INVENTOR(S)

Huy Nguyen et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 9, line 15, replace "signals" with -- signal --;

Column 9, line 18, delete "," after the word "detector";

Column 9, line 20, delete "," after the word "comparator";

Column 11, line 24, delete "," after the word "pre-driver";

Column 11, line 26, delete "," after the word "driver".

MAILING ADDRESS OF SENDER: MORGAN, LEWIS & BOCKIUS LLP 2 Palo Alto Square 3000 El Camino Real, Suite 700 Palo Alto, CA 94306 (650) 843-4000 1-PA/3565873.1 FORM PTO 1050

PATENT NO.

6,960,952 B2

No. of add'l. copies @ 30¢ perpage

==>

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,960,952 B2

DATED

November 1, 2005

INVENTOR(S)

Huy Nguyen et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 9, line 15, replace "signals" with -- signal --;

Column 9, line 18, delete "," after the word "detector";

Column 9, line 20, delete "," after the word "comparator";

Column 11, line 24, delete "," after the word "pre-driver";

Column 11, line 26, delete "," after the word "driver".

MAILING ADDRESS OF SENDER:
MORGAN, LEWIS & BOCKIUS LLP
2 Palo Alto Square
3000 El Camino Real, Suite 700
Palo Alto, CA 94306
(650) 843-4000
1-PA/3565873.1
FORM PTO 1050

PATENT NO.

6,960,952 B2

No. of add'l. copies @ 30¢ perpage

NOV 2 2 2005